


Products Custome Certification Factor Datas Here on Machinerie Facilities Product Health Contact Conclusion

INDESERE Sweater Limited

Introduction Products Customers Certifications, Hallmarks & Recognition Factory Details List Of Machineries Facilities Product Health Social Responsibility Contact Conclusion






indesore sweater limited is a modern sweater factory equipped with the latest and branded machineries from China, Taiwan, Japan, U.S.A, Italy, Turkey and U.K. The Bangladeshi sweater manufacturer's shares in global market are steadily growing in the wake of success of the ready-made sweater and also ready-made garments sector. indesore sweater limited is also willing to compete in the global market to provide high quality sweaters to the buyers and achieve it's desired goal. More over indesore sweater limited wants to prove itself as a well designed and well equipped sweater factory in Bangladesh, with skilled workers, relaxed working atmosphere and green environment.

indesore sweater limited ensures a healthy and breathing environment to it's workers, staff and the buyers. Safety and quality is a high priority for factory management.

This unit comprises of qualified and skilled workers with expert technicians. We are running with progressive management techniques and effective employee programs. indesore sweater limited also provides advanced training to it's staffs for healthier productivity as well as modern and better quality products.

indesore sweater limited is capable to produce high quality sweaters and able to sell it to the buyers of all over the world.





RALPH LAUREN CEIIO*

- H&M: Children, Men's & Ladies
- Celio: Men's
- Esprit: Ladies & Men's
- ZARA: Children & Ladies
- MYER : Ladies
- OVIESSE: Men's, Ladies & Children
- Ralph Lauren: Men's, & Children
- Guess: Men's, & Ladies







PRODUCTION CAPACITY :

The production capacity of Indesore sweater Limited is around (5,00,000 pcs) per month.

TURNOVER:

The annual turnover of the factory is around 30 mUSD.

WORK FORCE:

Sweater Limited

Approximately 3,000 workers and staffs will work together in the factory.

CURRENT FACILITY:

 Total Space
 :
 2,86,476 Se

 Work Space
 :
 2,73,000 Se

 Washing Space
 :
 7,000 Se

 Office Space
 :
 6,476 Se

(12)

2,86,476 Sqft. (Approx) 2,73,000 Sqft. (Approx) 7,000 Sqft. (Approx) 6,476 Sqft. (Approx)





| | SI.No. | Particulars of the Machinery | Туре | No. of Machine | Brand | Origin |
|---|--------|--|---------------------------------------|----------------|--|----------------------------|
| Ceres la companya de la compa | | | 14gg(7/10/12/14) | 85 | | Japan |
| | 01 | Computerized Flat Knitting Machine | 48* | 17 | Shima Seiki | |
| | | · · · · | 7gg(3.5/5/7) 48* 3gg(1.5/2/3) 48* | 1/ 1 | - | Japan |
| | | | | 346 | | Japan Obia a |
| | 02 | Computerized Flat Knitting Machine | 12gg, 52" 12gg, 48" | 135 | Guosheng, Hongajima, Mingde, Julong, Jinhao, Huma | China |
| | | | 12gg, 48" 12gg, 44" | 135 | | China |
| | | | 7gg, 52" | 56 | | China |
| | | | 7/5 Multi gg, 44" | 16 | | China |
| | | | 7/5 Multi gg, 44 7/5 Multi gg, 48" | 63 | | China |
| | | | 5gg, 52" | 8 | | China |
| | | Winding Machine | 8 Spindle | 22 | D.H.Euro | China |
| C moc | 03 | Winding Machine | 48 Spindle | 1 | HI TECH | |
| | | Winding Machine | 24 Spindle | 2 | | НКБ |
| | | Winding Machine | 8 Spindle | 1 | | TING |
| | | Knitting Auto Transfer | 2 X 1 | 675 | | China |
| | 05 | Semi Auto Knitting Machine | 12gg, 36" | 10 | 1 | China |
| | 06 | Auto Placket Machine | 12gg, 00 | 17 | D.H.Euro | China |
| | 07 | Dial Linking Machine | 6gg | 18 | | China |
| | 08 | Auto Drawstring Machine | 12gg | 4 | | China |
| | 09 | Dial Linking Machine | 10gg | 1 | | China |
| | 10 | Dial Linking Machine | 5gg | 1 | | China |
| | 11 | Dial Linking Machine | 8gg | 114 | | China |
| | 12 | Dial Linking Machine | 14gg | 241 | | China |
| | 13 | Dial Linking Machine | 16gg | 345 | Feng Shen | China |
| | 14 | Overlock (Model-MO6714SBE644H/G39/Q141) | 4 Thread | 24 | & BROTHER | |
| | 15 | Button Hole (Model-LBH783NV) | Plain | 18 | | |
| | 16 | Button Stitch (Model-LK1903ASS301/MC596KSS) | Plain | 14 | | |
| | 17 | Bartek (Model-1900ASS/MC596KSS) | Plain | 20 | | Japan |
| | 18 | Flat Lock Machine | 5 Thread | 3 | | |
| | 19 | Plain Machine (Model-DDL8300N) | Single Needle | 102 | - NUL | |
| | 20 | Washing Machine 110 LBS full automatic | | 8 | | China |
| | 21 | Hydro Extractor (Capacity-200 LBS) | | 7 | NGAI SHING | China |
| | 22 | Auto Gas Dryer | Gas,200Lbs | 5 | NGAI SHING | China |
| | | , | Steam,200Lbs | 7 | | China |
| | 23 | Auto winding machine | 60 Head | 2 | | China |
| | 24 | Vaccume Table with Industrial Steam Iron | | 127 | | China |
| | 25 | Dust Cleaner | | 8 | | China |
| | 26 | Needle Detector [30+(22X5") Aperture | | 1 | Lock | UK |
| | 27 | Needle Detector [30+(22X5") Aperture | | 1 | Syntex | China |
| | 28 | Needle Detector (600MM (W) X 1500MM(H)) | | 2 | | |
| | 29 | Boiler (Capacity - 939kg each) | | 2 | Fulton | U.S.A |
| | 30 | Boiler (Capacity - 1565kg) | | 1 | Fulton | U.S.A |
| | 31 | Boiler with Double Burner (Diesel + Gas) Capacity - 01 ton | | 1 | NGAI SHING | China |
| | 32 | Mini Electric Boiler for Sample Room (Capacity 24 kgs) | | 1 | NGAI SHING | China |
| | 33 | Diesel Generator-Capacity 650 KVA | | 2 | FG Wilson | UK |
| 13 | 34 | Bus Bar & Trunking | | Full Set | Graziadio | Italy |
| | 35 | Cooling Fan | | 30 | | ltaly Deve silve le els |
| | 36 | Light Check | | 12 set | 0(0 | Bangladesh |
| | 37 | SafQ Snap Testing Apparatus with several testing kits | | | SafQ | Japan |
| Sweater Ling - | 38 | Moisture Meter Light meter | LUX Meter | | Aqua Boy Model LX-101 | Germany Taiwan |
| | 39 | | | | | |



- Open space for work as per the internationally accepted compliance law.
- Day-care center for the babies of the workers as per labor law policy.(i.e. clause no 94 of page 9098 in8th episode of the labor law act 2006).
- Medical room with specialized doctors and nurses with emergency supporting equipments & medicines as per labor law policy. (i.e. clause no 89 of page 9096 in 8th episode of the labor law act 2006).
- Space for prayer is available for the staff and workers.
- Dinning room facility for the staff and workers as per labor law policy. (i.e. clause no 92 of page 9097 in 8th episode of the labor law act 2006).
- Cooling fan is using for dust free breathing environment and to make the floor cool.
- 24 hours standby generator facility.
- Lift facility along with adequate stairs for the staff & workers as per labor law policy. (i.e. clause no 69 of page 9088 in 6th episode of the labor law act 2006).
- Clean and hygienic environment everywhere.
- Modern Fire fighting equipments and easy evacuation plan for emergency exit as per labor law policy. (i.e. clause no 62 of page 9085 in 6th episode of the labor law act 2006).
- Group insurance for all staff & workers as per labor law policy. (i.e. clause no 99 of page 9099 in 8th episode of the labor law act 2006).
- A well designed lay out & fire evacuation plan for easy exit.
- indesore sweater ltd is fully equipped with PA system & CC Camera.



 \cap

 \cap



- The following subjects will be treated as the effective facilities for our factory to ensure the working environment healthy and safe.
- Toilet : The most important issue for a factory is clean & hygienic toilets. indesore sweater limited arranged an adequate number of toilets & urinals for the workers & staff and maintained properly to minimize the sickness.
- Pure Drinking Water: We have installed complete pure drinking water system from China fully equipped with Multimedia filter, Activated Carbon filter, Water Softer & RO system to have safe water for everyone in the factory.
- Lift : Lift facility is much more important for a modern factory, indesore sweater limited has both cargo and passenger lift facility for the betterment of the factory.
- Floor Plan : Working environment and productivity depends on the adequate and effective floor plan. indesore sweater limited provide it's staff a spacious and easy going corridors & space for easy working.
- Evacuation Plan : Evacuation plan is very much important for a factory to save the life of the workers & staff if any accident occurs.

indesore sweater limited arranged a well designed evacuation plan with 4 wide stairs to evacuate as soon as possible for saving life and important documents or assets.





profile



S 🔇

Sweater Limited

D



Letter of Recognition

The Accord on Fire and Building Safety (Accord) hereby recognizes that:

Indesore Sweater ltd. (9492) Dager Chala, National University, Gazipur Sadar, Gazipur

Has successfully completed all remediation measures required from the Accord initial inspections for fire, electrical, and structural safety conducted in August 2014.

Accord engineers have physically verified that all items of the corrective action plan, developed from the Accord initial inspections and approved by the Accord Chief Safety Inspector, have been correctly repaired¹.

The Accord initial inspections covered minimum life safety issues in the areas of fire, electrical, and structural safety based on an inspection standard developed with the Government of Bangladesh and national and international safety engineers through the facilitation of the ILO.

Factory safety is a continuous process which requires regular monitoring, maintenance, and in-factory safety systems and practices. The Accord will continue to support the factory managers and workers in institutionalizing and further advancing such culture of safety and health at the factory.

The Accord extends our congratulations to *Indesore Sweater ltd. (9492)* for achieving this safety milestone.

Rob Wayss Executive Director Stichting Bangladesh Accord Foundation Accord on Fire and Building Safety in Bangladesh

Date: 21/10/2019

Accord recognized indesore sweater ltd. For a successful completion of all remediation measures from the Accord initial inspection on Electrical, Fire & Structural Safety (1)

Ο

 \cap

¹This letter of recognition verifies that the factory has successfully remediated all items from the limited initial Accord inspection, and that the items in the corrective action plans were in a correct state of repair at the time of the verification inspection. This letter of recognition should not be considered to be a certification or endorsement on the part of the Accord.



We ensure Button Pull test check for the baby product We make sure the hazards chemical free product as per international law. We have 100% needle detection for the garments to make sure metal free product We always use oekotex certified yarn & accessories. We ensure insect free environment for the garments. We control moisture with in acceptable limit.





Water: We have Effluent Treatment Plant (ETP) to treat water before discharging into nature. As per our social responsibility we ensure complete treatment of used water before discharging to the environment.

Electrical Safety: We are using complete BUS-BAR TRUNKING system from Italy & Turkey to ensure safe wiring of electricity thus saving of the energy & safety of the factory.

Energy: We are using complete LED light source (Light Emitting Diodes) from China for the full factory which help us to save more than 50% energy and thus more effective, social, friendly.

Fire Safety: Smoking Detection System- we have installed addressable smoking detection system from UK which ensures immediate finding out the emergency location. More over we have MIMIC DISPLAY from UK which is a most modern technology in this category that gives you visual display of floor lay out indicating with a light exact pointing to the emergency place.

Hydrant System: We installed complete automatic Hydrant System from UK & Malaysia with Jockey Pump, Electric Driven Pump, and Diesel Pump along with most modern Hose, Pillars, and Extinguishers etc.

Sprinkler System: We have installed automatic Sprinkler system from UK to have more safety in regards to fire.

Fire Door: We have installed UL Rated fire doors from National Fire Fighting Manufacturing NAAFCO (FZCO) Dubai to ensure safety of the workers.

ETP Treated Water recycle: We are reducing apperx. 10% Production water consumption by the process of water recycle, which is treated by the ETP.



(1)

Factory

Deger Chala, PO. National university, Gazipur Sadar. Gazipur, Bangladesh. Telephone : 88 02 9293771 Fax : 88 02 9293780 E-mail : info@indesore.com

Bank Details

The City Bank Limited Gulshan Avenue Branch City Bank Center, (2nd Floor) 136, Gulshan Avenue, Gulshan-2,Dhaka-1212. Phone # +88 02 8813483 / 8814375, Ext-1391 Swift Code : CIBLBDDH, E-mail: noor.hossan@thecitybank.com, tsd@thecitybank.com

Contact persons


Tareaq TAREAQUZZAMAN Managing Director Contact : 017 130 31 138 E-mail : tareaq@indesore.com Milon ROKUNUZZAMAN Chairman Contact : 017 115 60 770 E-mail : milon@indesore.com

enquiry : info@indesore.com





conclusion



indesore sweater limited mainly focused on the best quality product with the most modern machineries and equipments and also the most effective organizational policies as well as the experienced workers, we can say that we will be able to enter in the market promptly and achieve the desired goal.

Finally our technically sound, well experienced, professional and dedicated workforce of each department and product fiscal management have placed us in a position to produce high quality sweaters and deliver in time to the entire satisfaction of our valued customers and assure to provide the best service out of Bangladesh.

Thus with a corporate social responsibility, we would like to stand in the global market with our signature image.

- profi

ወ

INDES RE Sweater Limited